

## **Complete Ari Saw line**

1. Log deck in 4 parts.
2. Step feeder.
3. Log crane.
4. REMA log scanner for top/butt.
5. Log haul conveyor.
6. Log turner.
7. Butt end reducer Bruks RR 1000.
8. Log haul conveyor with kick-off.
9. Infeed conveyor before debarker.
10. Debarker Cambio 66 with AirTen.
11. Guide work after debarker.
12. Log haul with kick-off.
13. Cross conveyor.
14. Step feeder.
15. Log haul conveyor in to saw line.
16. SAWCO scanning system.
17. ARI log turner.
18. ARI infeed conveyor before chipper canter.
19. Ari chipper canter SKR 600.
20. ARI Scragg saw KS - 12
21. Roll conveyor with board separator.
22. Chain conveyor with kick-off for cants.
23. Cross conveyor for cants.
24. Roll conveyor for cants.
25. Cross conveyor with movable swords.
26. Roll conveyor for cants.
27. Infeed conveyor with rolls and over press for infeed in to chipper canter BKR.
28. Chipper canter BKR 600.
29. Roll conveyor with guide wheels for infeed in to ARI DS 74 + 1.
30. Multi rip saw ARI DS 74 + 1.
31. Roll conveyor for separation of side boards and center pieces.
32. Roll conveyor with chain kick-off.
33. Cross conveyor to edger.
34. S-elevator with flap for drop down of rejects.
35. Infeed conveyor before edger.
36. Edger Vislanda KV 350.
37. Lath separator Vislanda SS360.
38. Cross conveyor for side boards.
39. Elevator for side boards up to sorting line.
40. Cross conveyor (curved) in to sorting line.
41. All conveyors in bottom floor for bark, chips and saw dust.
42. All hydraulics, electric and electronics for the line.